

TANDBERG MCU D1.1 Release Note

TANDBERG

D50178, Rev 1.0

Table of Contents

1. INTRODUCTION.....	3
2. NEW FEATURES IN D1.1	3
3. CHANGES AND IMPROVEMENTS IN D1.1 FROM D1.0	3
4. AUDIENCE FOR THIS RELEASE.....	3
5. GETTING THE SOFTWARE.....	3
6. INSTALLATION.....	3
7. REFERENCES.....	3

1. Introduction

This release note is to describe the changes, use, and installation of the D1.1 Software Release for the TANDBERG MCU released 10/25/02. D1.1 is a maintenance release only and includes no new functionality for the product.

2. New Features in D1.1

D1.1 is a maintenance only release. D1.1 includes no new features or functionalities over the previous version for the TANDBERG MCU D1.0

3. Changes and Improvements in D1.1 from D1.0

- Improved lipsync/video delay on lower bandwidths
- Improved video quality with 15 and 16 video sites
- E1 CRC4-setting is now working for each PRI separately

4. Audience for this release

D1.1 is intended for all installations of the TANDBERG MCU. All users of the TANDBERG MCU should upgrade their units to D1.1

5. Getting the Software

Customers should contact their reseller or maintenance provider for support and assistance with their TANDBERG products. There is not a separate upgrade patch to upgrade to D1.1 from D1.0. Upgrading to D1.1 will require the full D1.1 pkg file and a release key specific to the TANDBERG MCU to be upgraded. Contact your reseller or maintenance provider for the software file and release key.

6. Installation

Installation of D1.1 software can be accomplished through a local upgrade through the serial port, or over an IP network using the built-in FTP or WWW servers of the TANDBERG MCU. Please refer to document D10238 "How To Upgrade a TANDBERG Videoconferencing System" for detailed instructions on upgrading a TANDBERG video system.

7. References

TANDBERG Website
TANDBERG FTP Site

- <http://www.tandberg.net>
- <ftp://ftp.tandbergusa.com>